

## **APPENDIX C**

### SEO INSPECTION REPORTS

# ENGINEERS INSPECTION REPORT

JMU 4.6.64 FILE COPY

OFFICE OF THE STATE ENGINEER-DIVISION OF WATER RESOURCES - DAM SAFETY BRANCH  
1313 Sherman Street, Room 818, Denver, CO 80203, (303) 866-3581

DAM NAME Summitville Tailings W. DIV. 3 W. DIST. 21 DATE OF INSPECTION 10/3/00  
 DAM ID 210103 FILE NO. C- FOREST I.D. \_\_\_\_\_ DATE OF LAST INSPECTION 7/1/87  
by Water Committee  
 OWNER NAME \_\_\_\_\_ OWNER PHONE \_\_\_\_\_  
 ADDRESS \_\_\_\_\_ ZIP CODE \_\_\_\_\_  
 CONTACT NAME Austin Buckingham - CDPHE CONTACT PHONE 303-620-3000  
 CLASS 3 CAPACITY 763 AF SURFACE AREA 16 AC. HEIGHT 26 FT. CREST LENGTH 480 FT. CREST WIDTH 30.0 FT.  
 CURRENT RESTRICTION  (NO)  (YES) LEVEL \_\_\_\_\_ EPP ON FILE  (NO)  (YES) N/A SPWY WIDTH 16 FT. FBD. 4 FT. Z \_\_\_\_\_  
 INSPECTION PARTY REPRESENTING Jim Salmons Austin Buckingham Tom Hascarover Mike Tarning Angus Campbell  
CDPHE RMC BCR CDPHE

**DIRECTIONS:** MARK AN X FOR CONDITIONS FOUND AND UNDERLINE WORDS THAT APPLY. GIVE LOCATION AND EXTENT WITH NUMBER REFERENCE I.E. (25) ALL ALONG SLOPE, OR SHOW IT ON SKETCH.

**FIELD CONDITIONS OBSERVED**

WATER LEVEL - BELOW DAM CREST 11,222 (Spill elev) FT. BELOW SPILLWAY 11,122 (water level) FT. GAGE ROD \_\_\_\_\_  
 GROUND MOISTURE CONDITION: DRY ✓ WET \_\_\_\_\_ SNOWCOVER \_\_\_\_\_ OTHER \_\_\_\_\_

**UPSTREAM SLOPE**

PROBLEMS NOTED:  (0) NONE  (1) RIPRAP - MISSING, SPARSE, DISPLACED, WEATHERED  (2) WAVE EROSION-WITH SCARPS  
 (3) CRACKS-WITH DISPLACEMENT  (4) SINKHOLE  (5) APPEARS TOO STEEP  (6) DEPRESSIONS OR BULGES  (7) SLIDES  
 (8) CONCRETE FACING-HOLES, CRACKS, DISPLACED, UNDERMINED  (9) OTHER \_\_\_\_\_  
 Comments: (1) Riprap placed in mid 1970's not well-graded (2) erosion below riprap w/ wave scarps - riprap extends lower ~ 1/3 from crest (3) Whole slope appears steep

**CREST**

PROBLEMS NOTED:  (10) NONE  (11) RUTS OR PUDDLES  (12) EROSION  (13) CRACKS - WITH DISPLACEMENT  (14) SINKHOLES  
 (15) NOT WIDE ENOUGH  (16) LOW AREA  (17) MISALIGNMENT  (18) INADEQUATE SURFACE DRAINAGE  
 (19) OTHER \_\_\_\_\_  
 Comments: (16) Dip a crest near pump house (18) Apparent level based gravel road across crest

**DOWNSTREAM SLOPE**

PROBLEMS NOTED:  (20) NONE  (21) LIVESTOCK DAMAGE  (22) EROSION OR GULLIES  (23) CRACKS - WITH DISPLACEMENT  (24) SINKHOLE  
 (25) APPEARS TOO STEEP  (26) DEPRESSION OR BULGES  (27) SLIDE  (28) SOFT AREAS  (29) OTHER \_\_\_\_\_  
 Comments: (25) Upper 1/5 of dam steeper than remainder - probably due to maximum crest elevation of 115' (22) Erosion at both gorges  
lined w/ filter drains and stone fill ~1995

**SEEPAGE**

PROBLEMS NOTED:  (30) NONE  (31) SATURATED EMBANKMENT AREA  (32) SEEPAGE EXITS ON EMBANKMENT  
 (33) SEEPAGE EXITS AT POINT SOURCE  (34) SEEPAGE AREA AT TOE  (35) FLOW ADJACENT TO OUTLET  (36) SEEPAGE INCREASED/MUDDY  
 DRAIN OUTFALLS SEEN \_\_\_ No \_\_\_ Yes  (37) FLOW INCREASED/MUDDY  (38) DRAIN DRY/OBSTRUCTED  
 (39) OTHER 35' (30' max) adjacent to both R/R's Show location of drains on sketch and indicate amount and quality of discharge.  
 Comments: 35' (30' max) adjacent to both R/R's (34) At max section collected in pipe 1/2 in. dia. as high as 30 gpm (~15 gpm during use). Annual veg analysis performed

**OUTLET**

PROBLEMS NOTED:  (40) NONE  (41) NO OUTLET FOUND  (42) POOR OPERATING ACCESS  (43) INOPERABLE  
 (44) UPSTREAM OR DOWNSTREAM STRUCTURE DETERIORATED  (45) OUTLET NOT OPERATED DURING INSPECTION  
 INTERIOR INSPECTED  (120) NO  (121) YES  (46) CONDUIT DETERIORATED OR COLLAPSED  (47) JOINTS DISPLACED  (48) VALVE LEAKAGE  
 (49) OTHER \_\_\_\_\_  
 Comments: 45' (45' max) adjacent to both R/R's (45) Outlet not operated during inspection structure 1995 30' dia. 12" dia. valves

**SPILLWAY**

PROBLEMS NOTED:  (50) NONE  (51) NO EMERGENCY SPILLWAY FOUND  (52) EROSION WITH BACKCUTTING  (53) CRACK - WITH DISPLACEMENT  
 (54) APPEARS TO BE STRUCTURALLY INADEQUATE  (55) APPEARS TOO SMALL  (56) INADEQUATE FREEBOARD  (57) FLOW OBSTRUCTED  
 (58) CONCRETE DETERIORATED/UNDERMINED  (59) OTHER \_\_\_\_\_  
 Comments: \_\_\_\_\_

|                     |            |      |
|---------------------|------------|------|
| Conditions Observed |            |      |
| GOOD                | ACCEPTABLE | POOR |
| UPSTREAM SLOPE      |            |      |
| GOOD                | ACCEPTABLE | POOR |
| CREST               |            |      |
| GOOD                | ACCEPTABLE | POOR |
| DOWNSTREAM SLOPE    |            |      |
| GOOD                | ACCEPTABLE | POOR |
| SEEPAGE             |            |      |
| GOOD                | ACCEPTABLE | POOR |
| OUTLET              |            |      |
| GOOD                | ACCEPTABLE | POOR |
| SPILLWAY            |            |      |
| GOOD                | ACCEPTABLE | POOR |

See Guidelines on Back of this Sheet

**MONITORING**  
 EXISTING INSTRUMENTATION FOUND  (110) NONE  (111) GAGE ROD  (112) PIEZOMETERS  (113) SEEPAGE WEIRS/FLUMES  
 (114) SURVEY MONUMENTS  (115) OTHER Pressure transducer for reservoir depth.  
 MONITORING OF INSTRUMENTATION:  (116) NO  (117) YES PERIODIC INSPECTIONS BY:  (118) OWNER  (119) ENG.  
 Comments: (112) 3 piezometers installed 1999 (115) Q-trackers in each outlet pipe (2) to measure flowrate for outlet, PVC used to measure seepage @ prod

|                                     |            |            |
|-------------------------------------|------------|------------|
| <input checked="" type="checkbox"/> | GOOD       | MONITORING |
| <input type="checkbox"/>            | ACCEPTABLE |            |
| <input type="checkbox"/>            | POOR       |            |

**MAINTENANCE AND REPAIR**  
 PROBLEMS NOTED:  (60) NONE  (61) ACCESS ROAD NEEDS MAINTENANCE  (62) CATTLE DAMAGE  
 (63) BRUSH ON UPSTREAM SLOPE, CREST, DOWNSTREAM SLOPE, TOE  (64) TREES ON UPSTREAM SLOPE, CREST, DOWNSTREAM SLOPE, TOE  
 (65) RODENT ACTIVITY ON UPSTREAM SLOPE, CREST, DOWNSTREAM SLOPE, TOE  (66) DETERIORATED CONCRETE-FACING, OUTLET, SPILLWAY,  
 (67) GATE AND OPERATING MECHANISM NEED MAINTENANCE  (68) OTHER Panel at toe (seepage), upstream riprap  
 Comments: and heavy spillway channel erosion

|                                     |            |                         |
|-------------------------------------|------------|-------------------------|
| <input checked="" type="checkbox"/> | GOOD       | MAINTENANCE AND REPAIRS |
| <input type="checkbox"/>            | ACCEPTABLE |                         |
| <input type="checkbox"/>            | POOR       |                         |

**OVERALL CONDITIONS**  
 REMARKS: Presently exempt from Rules and Regulations for Dam Safety since the dam is included within the permit boundary of the current mining operation and has been removed from the normal inspection schedule.  
 Based on this Safety Inspection and recent file review, the overall condition is determined to be:  
 71 SATISFACTORY  72 CONDITIONALLY SATISFACTORY  73 UNSATISFACTORY

|                          |            |                    |
|--------------------------|------------|--------------------|
| <input type="checkbox"/> | GOOD       | OVERALL CONDITIONS |
| <input type="checkbox"/> | ACCEPTABLE |                    |
| <input type="checkbox"/> | POOR       |                    |

**ITEMS REQUIRING ACTION BY OWNER TO IMPROVE THE SAFETY OF THE DAM**

THIS IS THE MINIMUM ACTION YOU SHOULD TAKE. ADDITIONAL ACTION MAY BE NECESSARY PER YOUR ENGINEER'S ADVICE.

- MAINTENANCE - MINOR REPAIR - MONITORING**
- (80) PROVIDE ADDITIONAL RIPRAP: on upstream slope
  - (81) LUBRICATE AND OPERATE OUTLET GATES THROUGH FULL CYCLE: Annually
  - (82) CLEAR TREES AND/OR BRUSH FROM: \_\_\_\_\_
  - (83) INITIATE RODENT CONTROL PROGRAM AND PROPERLY BACKFILL EXISTING HOLES: \_\_\_\_\_
  - (84) GRADE CREST TO A UNIFORM ELEVATION WITH DRAINAGE TO THE UPSTREAM SLOPE: Superelevate to 4/5 slope & provide uniform elevation
  - (85) PROVIDE SURFACE DRAINAGE FOR: \_\_\_\_\_
  - (86) MONITOR: Seepage
  - (87) DEVELOP AND SUBMIT AN EMERGENCY PREPAREDNESS PLAN: If becomes Class 2 dam
  - (88) OTHER: Remove spillway obstructions 4/5 of spillway (pipeline and logs) & berm 4/5
  - (89) OTHER: Flatten and/or protect spillway channel slopes to protect from erosion

- ENGINEERING - EMPLOY AN ENGINEER EXPERIENCED IN DESIGN AND CONSTRUCTION OF DAMS TO:**
- (90) PREPARE PLANS AND SPECIFICATIONS FOR THE REHABILITATION OF THE DAM: \_\_\_\_\_
  - (91) PREPARE AS-BUILT DRAWINGS OF: Dam
  - (92) PERFORM A GEOTECHNICAL INVESTIGATION TO EVALUATE THE STABILITY OF THE DAM: \_\_\_\_\_
  - (93) PERFORM A HYDROLOGIC STUDY TO DETERMINE REQUIRED SPILLWAY SIZE: Determine if spillway capacity + reservoir capacity is adequate
  - (94) PREPARE PLANS AND SPECIFICATIONS FOR AN ADEQUATE SPILLWAY: \_\_\_\_\_
  - (95) SET UP A MONITORING SYSTEM INCLUDING WORK SHEETS, REDUCED DATA AND GRAPHED RESULTS: \_\_\_\_\_
  - (96) PERFORM AN INTERNAL INSPECTION OF THE OUTLET: \_\_\_\_\_
  - (97) OTHER: \_\_\_\_\_
  - (98) OTHER: \_\_\_\_\_
  - (99) OTHER: \_\_\_\_\_

**SAFE STORAGE LEVEL RECOMMENDED AS A RESULT OF THIS INSPECTION**

- (101) FULL STORAGE
  - (102) CONDITIONAL FULL STORAGE
  - (103) RECOMMENDED RESTRICTION
- RESTRICTED LEVEL - OFFICIAL ORDER TO FOLLOW
- \_\_\_\_\_ FT. BELOW DAMS CREST
  - \_\_\_\_\_ FT. BELOW SPILLWAY CREST
  - \_\_\_\_\_ FT. GAGE HEIGHT
  - \_\_\_\_\_ NO STORAGE-MAINTAIN OUTLET FULLY OPEN

REASON FOR RESTRICTION: \_\_\_\_\_

ACTIONS REQUIRED FOR CONDITIONAL FULL STORAGE OR CONTINUED STORAGE AT THE RESTRICTED LEVEL: Unsure whether dam is Class 2 or 3. Hydrology study to determine spillway size or amount of storage still to be completed. As built plans to be submitted by 11/15/00  
(91)(93)(86)(88)(89)

Engineer's Signature: [Signature] INSPECTED BY: [Signature]  
 Owner's Signature: [Signature] OWNER/OWNER'S REPRESENTATIVE: \_\_\_\_\_ DATE: 10/3/00  
 DC-185a-85 pp 2 of 2